

Cordova: Sand Storage Shed**FY2008 Request: \$1,253,000**
Reference No: 43239**AP/AL:** Allocation
Category: Transportation
Location: Cordova**House District:** Cordova/Southeast Islands**Estimated Project Dates:** 07/01/2007 - 06/30/2012**Appropriation:** Airport Improvement Program**Project Type:** Construction**Contact:** John Torgerson**Contact Phone:** (907)269-0724**Brief Summary and Statement of Need:**

Replace the existing 40 foot by 70 foot (10 foot ceiling) sand storage building with a new 40 foot by 80 foot structure at the Cordova Mudhole Smith Airport. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	FY2008	FY2009	FY2010	FY2011	FY2012	FY2013	Total
Fed Rcpts	\$1,253,000						\$1,253,000
Total:	\$1,253,000	\$0	\$0	\$0	\$0	\$0	\$1,253,000

<input type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

The existing structure was built by the maintenance crew in 1977 and has outlived its serviceable lifespan. The shed is too small which hampers sand deployment operations, and the lack of proper insulation in the walls and ceiling make it very costly to heat. The doors do not seal properly. New material placed in the building can take 10-12 days to thaw. A new building is needed to reduce maintenance and operating costs and improve efficiency.